Mr. R. Sand durk

36/01/2274 36/01/2274

pwd

Sub Divisional Engineer, Provincial Sub Division No. 3, PWD (B&R) Br., Sirsa Email ID: pwd-eepd1-sirsa@hry.nic.in, Phone: 01666-220530

To

DAV Centenary Public School Barnala Road Sirsa

Memo No. 143

dated 30-01-2024

Sub:-

Request for School Building Safety Certificate . (DAV Centenary Public School, Barnala Road Sirsa).

Ref:- Your application No. DAV /SSA/333 dated 07-11-2023.

In this connection it is intimated that the school building of DAV Centenary Public School, Sirsa was inspected by alongwith concerned JE. It was found from the visual inspection that the present condition of the building is satisfactory. The school building structure certificate is hereby issued for one year w.e.f 01-01-2024 to 31-12-2024.

- 1. No addition and alteration be made in existing school building.
- 2. Structural Safety Certificate is issued as per safety certificate given by B.B GERA BE (Civil Engg.), Sirsa dully verified by Principal, DAV Centenary Public School, Barnala Road Sirsa that building structure satisfy all applicable Indian Standard requirement and PWD specification.
- 3. All Procedural /legal/operational/Supervision matter and architectural/ functional detail shall be the responsibility of the owner/architect.

This is for your kind information and further necessary action please.

DA/ Nil

Sub Divisional Engineer, Provl Sub Division No.3, PWD B&R Bp, Sirsa

Endst. No.

Dated

Copy of above is forwarded to the Executive Engineer, Provl. Division No.1,PWD B&R., Br., Sirsa for information w.r.t. his office Endst no. 433 dated 23-1-2024.

DA/Nil

Sub Divisional Engineer, Provl Sub Division No.3 PWD B&R Br., Sirsa